

Message

**From:** COLLINS Jay [Jay.COLLINS@state.or.us]  
**Sent:** 3/20/2019 11:25:29 PM  
**To:** Ex. 6 PP / Ex. 7(C)  
**CC:** COLLINS Jay [Jay.COLLINS@state.or.us]; WHEELER Sarah [Sarah.WHEELER@state.or.us]; BATES Zebuliah [Zebuliah.Bates@state.or.us]  
**Subject:** RE: SoloPower followup

Ex. 6 PP / Ex. 7(C)

Ex. 6 PP / Ex. 7(C) representing LIT Industrial just called me. Ex. 6 PP / Ex. 7(C) asked about the last line of my Inspection Report before the Attachments section. It should read: "(LIT Industrial's actions do meet the criteria for SNC status.)". I am going to correct and re-issue the report to say "...do NOT meet...". This is embarrassing. In inserting this section I was trying to make plain LIT's responsible if not fully compliant actions in cleaning up the problem from SoloPower System's actions in abandoning this facility and not abating any hazards nor managing their hazardous wastes!

On a separate point, I asked about where Ex. 6 PP / Ex. 7(C) is with the final cost data for their abatement and cleanup work on site. I

Ex. 5 Deliberative Process (DP)  
**Ex. 5 Deliberative Process (DP)** Ex. 6 PP / Ex. 7(C) said that was a good estimate, and that Ex. 6 PP / Ex. 7(C) is in process collecting all of the business records and compiling the data. Ex. 6 PP / Ex. 7(C) would be getting that final cost evaluation to me, to you, and to officials representing Multnomah County. I did not get a timeframe on this.

Jay

**From:** Ex. 6 PP / Ex. 7(C)  
**Sent:** Wednesday, March 20, 2019 4:03 PM  
**To:** COLLINS Jay <Jay.COLLINS@state.or.us>  
**Subject:** RE: SoloPower followup

That's ok. Thanks for explaining. Ex. 6 PP / Ex. 7(C)

**From:** COLLINS Jay <Jay.COLLINS@state.or.us>  
**Sent:** Wednesday, March 20, 2019 3:53 PM  
**To:** Ex. 6 PP / Ex. 7(C)  
**Cc:** COLLINS Jay <Jay.COLLINS@state.or.us>; BATES Zebuliah <Zebuliah.Bates@state.or.us>  
**Subject:** RE: SoloPower followup

Ex. 6 PP / Ex. 7(C)

Thank you for asking.

A while back, Nick asked me if there was anything else. I asked him about BES' follow up on that and the contents of the unit with the downspout pipe in the lot.

He immediately contacted LIT Industrial. They replied with photographs taken inside the unit. It was a chiller. No product storage of any kind was observed. They say that only non-contact condensate went down this water line. LIT Industrial agreed to cement this connection closed once the chiller unit was moved. I believe this was completed. I don't think it's likely that the former tenant would have gone to the trouble of using this connection for disposal of hazardous chemistry from the plant. I have heard of no investigation of the contents/residues in this line.

I can certainly locate the actual records (email questions from BES, and LIT Industrial's response with photographs and narrative) if you think you'll need them.

Jay

Jay Collins  
Hazardous Waste Inspector  
Northwest Region  
Oregon DEQ  
(503) 229-5008  
[collins.jay@deg.state.or.us](mailto:collins.jay@deg.state.or.us)

---

**From:** Ex. 6 PP / Ex. 7(C)  
**Sent:** Wednesday, March 20, 2019 3:42 PM  
**To:** COLLINS Jay <[Jay.COLLINS@state.or.us](mailto:Jay.COLLINS@state.or.us)>  
**Subject:** RE: SoloPower followup

Jay,  
I forgot to follow up on this email. Did Nick find out anything regarding the downward pipe by the metal outbuilding? –

Ex. 6 PP / Ex. 7(C)

Ex. 6 PP / Ex. 7(C)  
**Special Agent**  
U.S. EPA R10  
805 SW Broadway  
Portland OR 97205

Ex. 6 PP / Ex. 7(C)

WARNING - THE INFORMATION CONTAINED HEREIN MAY INCLUDE LAW ENFORCEMENT SENSITIVE AND/OR PRIVACY ACT INFORMATION, THE FURTHER DISTRIBUTION OF WHICH (BEYOND THE RECIPIENTS TO WHOM IT HAS BEEN ADDRESSED) MAY BE IN VIOLATION OF FEDERAL INFORMATION SECURITY REGULATIONS, CIVIL AND/OR CRIMINAL LAW WITHOUT THE EXPRESSED PRIOR WRITTEN CONSENT TO RELEASE AND/OR DISSEMINATE FURTHER BY THE U.S. EPA-CID. IF YOU ARE NOT THE INTENDED RECIPIENT PLEASE CONTACT THE SENDER BY REPLY E-MAIL AND DESTROY ALL COPIES OF THE ORIGINAL MESSAGE AND ATTACHMENTS.

---

**From:** COLLINS Jay <[Jay.COLLINS@state.or.us](mailto:Jay.COLLINS@state.or.us)>  
**Sent:** Friday, January 25, 2019 3:59 PM  
**To:** Ex. 6 PP / Ex. 7(C)  
**Cc:** COLLINS Jay <[Jay.COLLINS@state.or.us](mailto:Jay.COLLINS@state.or.us)>  
**Subject:** SoloPower followup

Nick from City of Portland's Bureau of Env Services is checking on a last detail about the metal outbuilding and what appeared to be a discharge point. It might have been chiller condensate, he's checking.

Let me know when enough is enough or I will keep copying you.